In Re Appln. Michael Todd Appln. Serial No. 10/749,709

In the Specification

Please amend the specification as follows:

On page 2, lines 15-17: Bracket 44 may either be formed as a part of fan 42 and secured to housing [[16]] 18 or it may be a separate bracket attached to both fan 42 and housing [[16]] 18 by means of bolts or the like.

On page 3, lines 8-9: Mounting bosses 52 may be formed as a part of housing [[16]] 118 or may be formed as a part of fan 142.